


# ASSEMBLING INSTRUCTION 44-PBT980



1. The two squared metal sheets have to be taped on the floor.
2. The pulley, on the rubber cord, should to be fixed to the metal sheet with the ripping locks.
3. The scoring machine has to be ready to work. The cable plugs must be plugged into the machine. The cable should to be connected to fix place, e.g. the legs of the table, the scoring machine is placed on. This procedure is to save the cable from coming out.
4. The pulley on the cable, coming from the scoring machine, should to be connected to ripping locks, fitted on the end of the rubber cord.